



Due to Life Safety Code issues and that the building does not have a sprinkler system; the secondary egress door will need to be located here.

# Scheme #10r

August 17, 2023